

# U.S. Senate

## Desk Description and Condition Report

Desk No : **66.00072.000**

Paper Label No.(on shelf bottom): 51

Painted No. (on bottom): N/A

Other identifying labels or marks (specify location): Stretcher: 50, 51, LXXII / Top: (stamped) 50, (pencil) 72/ Drawer Bottom: outside - (paper) "Gail", (pencil) "Goldwater" ; inside - /Drawer Back: (pencil) 50 / Bottom of Shelf (other than paper label): / Drawer Blade: / Inside Case Back: / Inkwell: (pencil) 72

### Description of Desk

Dimensions (in inches)

	Overall	Orig. Desk*	Case	Shelf
Height	35 3/8	32		
Width (front)	28 3/4	26 1/2	25 3/4	
Width (rear)	27 1/4	24 5/8	24	
Depth	20	20	19 1/8	8 3/4

\* Note: Dimensions do not include "booster" blocks added to feet or writing top.

### Woods

Primary:

Mahogany

Mahogany veneer

Rosewood veneer

Other Wood (specify): \_\_\_\_\_

\_\_\_\_\_

Character of case mahogany:

Plain

Ribbon

Mottled

Crotch

Other

Secondary:

Element	Pine	Ash	Poplar	Mahog	Other
Drawer Sides				✓	
Drawer Bottom			✓		
Drawer Back			✓		
Case Interior			✓		
Drawer Front	✓				



## Condition of Desk

### Structure

Previous breaks in structural elements: Yes   
(shown on schematic)  
No

Current split or broken elements: Yes   
(shown on schematic)  
No

Other loose or damaged joinery: Yes   
(describe in narrative)  
No

Damage to drawer front: Extreme   
Moderate   
Minor

Drawer lock: relocated on face Yes

Drawer lock: resized on inside Yes

Cockbead on drawer front: Damaged   
(show on schematic)  
Missing   
Loose   
Replacements

Replaced drawer-side runners: Yes   
No

Replaced case-side runners: Yes   
No

Drawer bottom pieced-out at back edge: Yes   
No

Wear on Feet	Extreme	Moderate	Minor
Front	✓		
Rear			✓

Number of loose spindles: No: 1

Number of replaced spindles: (show on schematic) No: 1

Replaced veneers and cross-banding: Yes   
(show on schematic)  
No

Missing veneers and cross-banding: Yes   
(show on schematic)  
No

Delaminated/loose veneers & cross-banding: Yes   
(show on schematic)  
No

Shelf supports: Original/old   
New/recent   
Missing

Spindle support board in case: Yes   
No

**Finish**

Age	Excellent	Good	Fair	Poor
New			✓	
Old				
Unk.				

Note: Describe finish problems in narrative.

**Hardware/Attachments**

Item	Mismatch	Missing	Damaged
Knob (L)	✓		
Knob (R)			

Toe cap size:	Right toe: 19a
	Left toe: 19a